DONGGUAN COWINT NEW MATERIAL TECHNOLOGY CO.,LTD
No.2,West Industrial Road of Jiaoli,Zhongtang Town,Dongguan
Tel: +86-769-88882603 Web:www.cowint.com
E-mail: info@cowint.com

Technical data sheet
CTP-PE01 Acrylic Polymer in Primary Forms

Characteristics :

1 .High elasticity, soft, easy times thicker than the market thick version of printing fewer half;

2 .Has the advantages of simple operation, high fastness, washing (60 degrees temperature);

3 .Good production stability

Use range:

For screen printing.

Usage method:

Preparation tools: Prepare adhesive tools and a household hair dryer.

Gluing technique: Use a yellow gluing scraper to evenly apply the photosensitive adhesive, paying attention to the angle and force to ensure even gluing. When the photosensitive adhesive cannot be fully applied, it is not advisable to rush to replenish the adhesive. Instead, adjust the scraper angle to greater than 60 degrees and apply downward pressure to drive out the uncoated area and fill it with the already applied adhesive. Lightly apply at a small angle (less than 45 degrees) and repeat the operation until the front and back are fully and evenly coated.

Gluing environment: Gluing operations should be carried out in a dark environment, avoiding direct sunlight.

Drying stage: After the glue coating is completed, it immediately enters the drying stage, and the residual photosensitive glue on the scraper should be cleaned in a timely manner. If there is a large amount of glue, you can use a hair dryer for warm air drying, but be careful not to overheat and cause the screen to break. Focus on drying around until the photosensitive glue is completely dry.

Attention: When applying glue, avoid contact with the skin and wear appropriate protective equipment. The coated screen should not be exposed to the air to avoid affecting the drying effect.

Storage conditions:

The storage container should be avoided in low temperature and high temperature 0 ℃ under 40 ℃and above. Please use within 1 years.

Suggestions:

1 kinds of color, do not exceed the normal standard;

2, test shall ensure that the stamp is completely dry, otherwise it will affect the test results;

3, if not after heat treatment, to achieve the best effect of this product, recommended CT-28, CT-29 and other additives, to accelerate the crosslinking rate or extend the natural air dry time.

4, if you use ordinary (non dedicated screen plate screen printing, the screen) under the four corresponding point pad printing effect will be more obvious.

In verbal or written just the technical advice to show our Companies sincerity, but for our products ,the user companies still have your responsibility for test, to verify whether is suitable for the process and to use; Given the

use of the products of our company process conditions are not my company control, and therefore should be fully responsible by the users themselves.